



Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
FIRTH PARK AVENUE	o/s 45 (8th tree downhill)	TR: Felling	F/W mounded by shallow rooting, will be damaged upon planing off	Acer pseudoplatanus	Plant in existing pit o/s 45 (same position as felled tree)	Liquidambar styraciflua 'Worpl
FIRTH PARK AVENUE	o/s 37	TR: Felling	F/W mounded by shallow rooting, will be damaged upon planing off	Acer pseudoplatanus	Plant in new 800mm pit o/s 37 (same position as felled tree)	Liquidambar styraciflua 'Worpl
FIRTH PARK AVENUE	o/s 35	TR: Felling	F/W damaged/uplifting by shallow rooting	Acer platanoides	Plant in new 800mm pit o/s 33-35 (same position as felled tree)	Liquidambar styraciflua 'Worpl
FIRTH PARK AVENUE	o/s 39	TR: Felling - large scaffold limb lost (probably struck by skip lorry)	TR: Felling - large scaffold limb lost (probably struck by skip lorry)	Acer platanoides	New 800mm pit o/s 39 - same location as original	Liquidambar styraciflua 'Worpleston'
FIRTH PARK AVENUE	o/s 47 (2nd tree downhill)	TR: Felling	Stem wounding @ 2m, poor specimen	Acer pseudoplatanus	Plant in existing pit o/s 47 (same position as felled tree)	Liquidambar styraciflua 'Worpl
FIRTH PARK AVENUE	o/s 47 (4th tree down hill)	TR: Felling	Leading stem dead, decayed back down trunk	Acer pseudoplatanus	Plant in existing pit o/s 47 (same position as felled tree)	Liquidambar styraciflua 'Worpl
FIRTH PARK AVENUE	o/s 45 (7th tree downhill)	TR: Felling	F/W mounded by shallow rooting, will be damaged upon planing off	Acer pseudoplatanus	Plant in existing pit o/s 45 (same position as felled tree)	Liquidambar styraciflua 'Worpl